

REFERENCE:	TSB: 08-269-26 GROUP 08 - Electrical	Date:	July 8, 2026	REVISION:	–
VEHICLES AFFECTED:	2023 (DS) RAM 1500 Pickup This bulletin applies to vehicles equipped with: • Uconnect 3 with 5" Display (Sales Code UCA). • Uconnect 4 Nav With 8.4" Display radio (Sales Code UJQ). • Uconnect 4C Nav With 8.4" Display radio (Sales Code UCQ). • Uconnect 5C With 8.4" Display radio (Sales Code UED).			MARKET APPLICABILITY: ☒ NA☐ IAP ☐ EE☐ MEA ☐ SA☐ CH NOTE: This bulletin applies to the North America market.	
CUSTOMER SYMPTOM:	Customers may experience the following: • Trailer brake setting in radio cannot be changed.				
CAUSE:	Undetermined				

DISCUSSION:

Trailer brake setting in radio cannot be changed. This is a known issue which engineering is investigating for root cause. Radio replacement is not recommended.

POLICY:

Information Only

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.