

Technical Service Bulletin (TSB)
**Uconnect® Screen Image Changes Size,
Moves Or Is Out Of Place Unprompted**

REFERENCE:	TSB: 08-270-26 GROUP: 08 - Electrical	Date:	July 10, 2026	REVISION:	—
VEHICLES AFFECTED:	2022 - 2024 (DT) RAM 1500 Pickup This bulletin applies to vehicles equipped with a Uconnect 5 Nav W 12.0" Display (Sales Codes UBQ and UEQ).			MARKET APPLICABILITY: ☒ NA☐ MEA ☐ SA☐ IAP ☐ EE☐ CH NOTE: This bulletin applies to the North America markets.	
CUSTOMER SYMPTOM:	Customers may experience the following: The Uconnect® screen image changes size, moves or is out of place unprompted.				
CAUSE:	Under investigation				

DISCUSSION:

This Information Only bulletin contains information regarding when customers experience the Uconnect® screen image unexpectedly changes size, moves or is out of place. This symptom is currently under investigation. **Do not replace the radio for this symptom.**

POLICY:

Information Only