

Technical Service Bulletin (TSB)
Missing Hood Silencer Pad

REFERENCE:	TSB: 23-025-26 GROUP: 23 - Body	Date:	July 11, 2026	REVISION:	23-027-22
VEHICLES AFFECTED:	2022 (B1) Jeep Renegade This bulletin applies to vehicles built on or after February 03, 2022 (MDH 0203XX) and on or before June 07, 2022 (MDH 0607XX).			MARKET APPLICABILITY: ☐ NA☐ CH ☐ EE☐ IAP ☒ SA☐ MEA NOTE: This bulletin applies to the South America markets.	
CUSTOMER SYMPTOM:	Customers may comment on the following: Hood silencer pad is missing.				
CAUSE:	Lack of assembly				

This bulletin supersedes Service Bulletin 23-027-22, dated July 07, 2022, which should be removed from your files. This is a complete revision and no asterisks have been used to highlight revisions.

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 22-131, date of issue July 07, 2022. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.

REPAIR SUMMARY:

This bulletin is involves installing a hood silencer pad.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
23-02-91-94	Silencer Pad, Installation (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.
Failure Code	ZZ	Service Action	

SPARE PARTS:

Qty	Part No.	Description	Notes
1	Mopar - 68625557AA EMEA - 51980005	Silencer, Hood	
10	Mopar - 68625560AA EMEA - 46804433	Retainers/Clips, Silencer	

DIAGNOSIS:

If the customer describes any of the symptoms listed above in the customer symptom section, perform the Repair Procedure.

REPAIR PROCEDURE:

1. Install missing hood silencer. Refer to the detailed service procedures available in DealerCONNECT> Service Library under: 23 Body / Hood / Hood / Installation > Step 6 [Fig. 1](#).



Fig. 1
Location For Silencer Pad

NOTE: After applying this TSB, it is not necessary to send DID-I or DID-A.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.