

9100853

07/06/2026

MY 25-27 DT 25-26 DJ 25-26 D2

GPOP - Issue Review System

Part Number: 68574286A\$, 68574287A\$, 68574290A\$, 68605848A\$

Part Description: SWITCH Power Window

Issue Description: 25-26 DJ and D2. Driver door mirror switches are sticking down. This is being caused by excess trim panel material extending into the switch opening which puts pressure on the switch bezel. Material needs to be removed from the opening. Reference SOL S2523000066.