

Technical Service Bulletin (TSB)
Unable To Clear C1494-07 And C14A9-00 After 45A Recall

REFERENCE:	TSB: 08-292-26 GROUP: 08 - Electrical	Date:	July 23, 2026	REVISION:	–
VEHICLES AFFECTED:	2016 - 2017 (KL) Jeep Cherokee This bulletin applies to vehicles equipped with a 2.4L I4 MultiAir Engine (Sales Code ED6).			MARKET APPLICABILITY: ☒ NA☐ MEA ☐ SA☐ IAP ☐ EE☐ CH NOTE: This bulletin applies to the North America market.	
CUSTOMER SYMPTOM:	Technicians may experience the following: wiTECH displays a mismatch error after performing recall 45A.				
CAUSE:	Under investigation				

DISCUSSION:

This bulletin is to inform service technicians if DTCs C1494-07 and/or C14A9-00 remain active following completion of Recall 45A, verify recall completion requirements and perform all currently published diagnostic procedures. **Do not repeat the recall procedure multiple times in an attempt to clear the DTCs.** Document all diagnostic results and open a STAR case with supporting vehicle scan data. Engineering is investigating this condition.

POLICY:

Information Only

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.