



Connection offline

Technical Service Bulletin

Transaction No.: **2081723/2**

93 A3 PHEV: electric drive system warning lamp lights up/DTCs under: 008C

Release date: Jul 16, 2026

Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment
A3 Sportback e-tron	2016 – 2018	All	With PR Code: 0K3

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised <i>Service</i> (Updated verbiage)
1	04/22/2026	Initial publication

Customer states:

- The red “electric drive system warning” lamp light is present.

and/or

- The vehicle has no drive.

and/or

- The drive system cannot be activated.

Workshop findings:

- The customer statement can be reproduced.

and/or

- At least one of the following DTC entries is stored (active/static) in the control unit for Hybrid battery management (diagnostic address 008C):
 - **U01A000**: Cell module control unit 1, no communication
 - **U01A100**: Cell module control unit 2, no communication
 - **U01A200**: Cell module control unit 3, no communication
 - **U01A300**: Cell module control unit 4, no communication
 - **U01A400**: Cell module control unit 5, no communication
 - **U01A500**: Cell module control unit 6, no communication
 - **U01A600**: Cell module control unit 7, no communication

- **U01A700:** Cell module control unit 8, no communication
- **P058D00:** Battery monitoring voltage monitoring implausible signal
- **P0AA500:** Hybrid/EV Battery Negative Contact Circuit Stuck Open
- **P0A7D00:** Hybrid Battery Pack State of Charge Low

Technical Background

Not applicable.

Production Solution

Not applicable.

Service

Working through test plan for event memory entries and performing resulting work

- Work through the test plan for the DTC entries specified in the workshop findings according to GFF: The test plan for event memory entry P0A7D00 should be worked through as a priority.
 - Work resulting from this must be performed as specified in GFF/ELSA.

Warranty

Claim Type:	• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	2706		
Damage Code:	0040		
Labor Operations:	GFF	0150 0060	Time stated on the diagnostic protocol
	GFF	0150 0010	See SRT with associated operations
Claim Comment:	As per TSB 2081723/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Please note the information on predecessors and items that are included and excluded in the repair operations, as well as any associated tasks.

Additional Information

All part and service references provided in this TSB (**2081723**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, LLC / Audi Canada Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, LLC / Audi Canada Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or

otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.