

Technical Service Bulletin (TSB)
Malfunction Indicator Lamp (MIL) With
Diagnostic Trouble Code (DTC) P0607

REFERENCE:	TSB: 08-310-26 GROUP: 08 - Electrical	Date:	August 7, 2026	REVISION:	—
VEHICLES AFFECTED:	2026 (WL) Jeep Grand Cherokee / Grand Cherokee L This bulletin applies to vehicles equipped with 2.0L Hurricane 4 Turbo W/ESS (Sales Code EC7).			MARKET APPLICABILITY: ☒ NA☐ MEA ☐ SA☐ IAP ☐ EE☐ CH NOTE: This bulletin applies to the North America market.	
CUSTOMER SYMPTOM:	Customers must experience a Malfunction Indicator Lamp (MIL) illumination and the vehicle must exhibit/set the following Diagnostic Trouble Code (DTC): - P0607-00 - ECU Internal Performance. Customers may also comment on the following: - The check engine lamp is illuminated on the Instrument Panel Cluster (IPC) when the vehicle is started.				
CAUSE:	Powertrain Control Module (PCM) software				

DISCUSSION:

This Information Only bulletin provides guidance for a customer-reported condition in which the check engine lamp illuminates when the vehicle is started. Upon inspection, the technician will find DTC **P0607-00 - ECU Internal Performance**. The technician is to clear the DTC. If the DTC does not reset after clearing, return the vehicle to the customer. If the DTC resets after clearing, replace the PCM.

A PCM update is expected to be released in Q3 2026 for this issue.

POLICY:

Information Only.