

**Technical Service Bulletin (TSB)**  
**Missing Cargo Boxes**

|                    |                                                                                                                                                        |       |                |                                                                                                                                                                                                                                                                                                                 |           |
|--------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------|-------|----------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|
| REFERENCE:         | TSB: 23-032-26<br>GROUP: 23 - Body                                                                                                                     | Date: | August 7, 2026 | REVISION:                                                                                                                                                                                                                                                                                                       | 23-078-23 |
| VEHICLES AFFECTED: | 2023 (B1) Jeep Renegade<br>This bulletin applies to vehicles built on or after March 24, 2023 (MDH 0324XX) and on or before May 25, 2023 (MDH 0525XX). |       |                | MARKET APPLICABILITY:<br><div><input type="checkbox"/> NA<input type="checkbox"/> CH</div> <div><input type="checkbox"/> EE<input type="checkbox"/> IAP</div> <div><input checked="" type="checkbox"/> SA<input type="checkbox"/> MEA</div><br><b>NOTE:</b> This bulletin applies to the South America markets. |           |
| CUSTOMER SYMPTOM:  | Customers may comment on the following: <ul style="list-style-type: none"><li>Excessive noise from the rear of the vehicle.</li></ul>                  |       |                |                                                                                                                                                                                                                                                                                                                 |           |
| CAUSE:             | Missing cargo boxes Fig. 1                                                                                                                             |       |                |                                                                                                                                                                                                                                                                                                                 |           |

This bulletin supersedes Technical Service Bulletin (TSB) 23-078-23, date of issue June 27, 2023, which should be removed from your files. This is a complete revision and no asterisks have been used to highlight revisions.

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 23-192, date of issue June 27, 2023. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library.



**Fig. 1**  
Cargo Box Missing

**REPAIR SUMMARY:**

This bulletin involves installing cargo boxes to the vehicle.

**CLAIMS DATA:**

| Labor Operation No: | Labor Description                           | Skill Category                     | Labor Time |
|---------------------|---------------------------------------------|------------------------------------|------------|
| 23-21-16-92         | Cargo Boxes - Install<br>(0 - Introduction) | 6 - Electrical and Body<br>Systems | 0.1 Hrs.   |
| Failure Code        | ZZ                                          | Service Action                     |            |

**SPARE PARTS:**


| Qty | Part No.                             | Description          | Notes |
|-----|--------------------------------------|----------------------|-------|
| 1   | 7095207 - EMEA<br>7UC76LXHAA - Mopar | Cargo Box Left Side  |       |
| 1   | 7095208 - EMEA<br>7UC77LXHAA - Mopar | Cargo Box Right Side |       |

**DIAGNOSIS:**

If the customer describes any of the symptoms listed above in the customer symptom section, perform the Repair Procedure.

**REPAIR PROCEDURE:**

1. Open the liftgate.
2. Lift up on the load floor.
3. Install the left and right cargo boxes [Fig. 2](#).



**Fig. 2**  
Cargo Boxes Installed

1 - Left Cargo Box  
2 - Right Cargo Box

4. Close the load floor.
5. Close the liftgate.

**NOTE:** After applying this TSB, it is not necessary to send DID-I or DID-A.

**POLICY:**

Reimbursable within the provisions of the warranty.

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*