

Technical Service Bulletin (TSB)
Headliner Delamination

REFERENCE:	TSB: 23-033-26 GROUP: 23 - Body	Date:	August 7, 2026	REVISION:	23-066-23
VEHICLES AFFECTED:	2023 (B1) Jeep Renegade This bulletin applies to vehicles built on or after October 10, 2022 (MDH 1010XX) and on or before May 10, 2023 (MDH 0510XX).			MARKET APPLICABILITY: ☒ NA☐ CH ☐ EE☐ IAP ☒ SA☐ MEA NOTE: This bulletin applies to the South America and North America markets.	
CUSTOMER SYMPTOM:	Customers may experience the following: The headliner is delaminating (bubbling) Fig. 1.				
CAUSE:	Poor adhesion				

This bulletin supersedes Technical Service Bulletin (TSB) 23-066-23, date of issue June 08, 2023, which should be removed from your files. This is a complete revision and no asterisks have been used to highlight revisions.

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 23-161, date of issue June 08, 2023. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library.




Fig. 1
Headliner Delamination (Bubbling) Examples

REPAIR SUMMARY:

This bulletin involves replacing the headliner.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
23-20-45-9N	Headliner - Replace (1 - Semi-Skilled)	6 - Electrical and Body Systems	2.1 Hrs.
Failure Code	ZZ	Service Action	

SPARE PARTS:

Qty	Part No.	Description	Notes
1	7TS63DX9AA - Mopar 100268018 - EMEA	Headliner	Roof Trim Color Black
1	7TS64MS7AA - Mopar 100267256 - EMEA	Headliner	Roof Trim Color Grey

DIAGNOSIS:

If the customer describes any of the symptoms listed above in the customer symptom section, perform the Repair Procedure.

REPAIR PROCEDURE:

1. Replace the headliner. Refer to the detailed service procedures available in DealerCONNECT/Service Library under: Service Info>23 - Body / Interior / Headliner / Removal and Installation.

NOTE: After applying this TSB, it is not necessary to send DID-I or DID-A.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.