



SSM 55103 2024-2026 Nautilus - Rear Lamp Assembly (Rear Mounted Deck Lid Lamp Assembly) Replacement

Some 2024-2026 Nautilus vehicles may exhibit an inoperative segment or individual light emitting diode (LED) in the rear mounted deck lid lamp assembly (part of the rear lamp assembly). To correct this condition, replacement of the finished assembly (13A565) is not required. To repair, replace the rear mounted deck lid lamp sub-assembly (13434) and transfer components from the original rear liftgate lamp. Refer to Workshop Manual (WSM), Section 417-01 > Removal and Installation > Rear Lamp Assembly and perform Steps 9-11.