

Service

Chassis ID	Path
	861/Parts/Technical service bulletins/Service
Model	Identity
VN (4)	198265858
Publish date	ID/Operation
8/26/2026	V-861-001

Under Hood Contamination Prevention

V-861-001

(August 2026)

Valid for

All Volvo VN(4) trucks.

Case description

Under Hood soiling during winter season due to openings in front of the bumper.

Action

Replace the open bumper ducts with closed bumper ducts to partially resolve the issue. Follow the Impact instruction operation ID 8611-03-02-21 to replace the bezel panel.

Required Parts

Part Number	Description	Qty
26051660	Bumper Bezel with Fog Lamp, LH	1
26051665	Bumper Bezel with Fog Lamp, RH	1
OR		
26051668	Bumper Bezel W/O Fog Lamp, LH	1
26051671	Bumper Bezel W/O Fog Lamp, RH	1

Issued by

Technical Service