

D151 – WIRELESS CHARGER INOPERATIVE

UPDATE PRIOR TO SALE



AFFECTED MODELS	27MY Range Rover and Range Rover Sport
VOLUME AFFECTED	2425 US
REPAIR	A potential concern has been identified on certain vehicles, where the wireless charger is unable to charge an iPhone. A soft ware update to the Wireless Device Charger Module (WDCM) is required.
REPAIR TIME	0.2 hrs +DIDO
CAMPAIGN LAUNCH	August 18th, 2026
NOTES	Retailers are required to hold from sale, all affected vehicles in their inventory until the repair is completed. All affected VINs are flagged in TOPIx, the warranty portal and retailer inventory reports are available in BBSS.