



Service Bulletin

Bulletin No.: PIT6455C

Date: August, 2026

PRELIMINARY INFORMATION

Subject: Service Driver Assist message with DTCs B1B2F and U1624

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 1500	2025-2026		All	All	All	All
GMC	Sierra 1500	2025-2026		All	All	All	All

Involved Region or Country	North America
Condition	A customer may comment that the Service Driver Assist message is displayed in the DIC. Dealer will find DTC B1B2F Telematics Control Module and U1624 Image Processing Control Module set current.
Cause	Software Anomaly

Correction

An over-the-air (OTA) update has recently begun a phased rollout and will continue to be deployed to vehicles over the coming months. Refer to PIT6529: Intermittent Loss of Connectivity GPS or Wi-Fi Due to OnStar Module (K73 Telematics Control Module) Anomaly to verify if OTA has been released to vehicle and if not, follow information to request the OTA.

Version	4
Modified	11/20/2025 - Created on 05/4/2026 - Update to the Correction section 07/06/2026 - Update to the Correction section 08/26/2026 - Update to the Correction section

