



Connection offline

Vehicle-specific service

Transaction No.: **2083125/1**

01 PSS Engine, drive system fault, fuel pressure sensor - malfunction P119A and/or P119B - 3.0 ltr. V6 TFSI

Release date: Aug 27, 2026

Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment			
S5, A6, SQ5, and SQ5 Sportback	2026	All	Engine type DWVA			
			00A5 - Front sensor for driver assistance systems			
			Software part number	Software version	Hardware part number	Hardware version
			*	0801	*	*

Customer statement:

- Drive system fault active in instrument cluster.

Workshop findings:

One or both of the following event memory entries are logged in the engine control unit (address 0001).

- **P119A00** Fuel pressure sensor Malfunction – symptom 13432 – static/intermittent.
- **P119B00** Fuel pressure sensor 2 Malfunction – symptom 17873 – static/intermittent.

Technical Background

Software issue (engine control unit, address 0001) with rail high-pressure diagnostics.

Production Solution

Not applicable

Service

Please postpone repair. A technical measure is currently being analyzed. This analysis is expected to be completed in the 4th quarter of 2026.

Note: The target date communicated here is based on planning and is not binding. During the validation, technical and regulatory approval of measures, there may be delays or hindrances in providing the measure throughout the entire process. This must be considered accordingly when communicating with customers.

Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in Audi Now; *Service | AU-US > Pending Service Solutions (PSS)*.

Warranty

There is no reason to replace parts or attempt repairs. Unjustified work/replacement parts will be charged back. Invoicing under warranty is not permitted.

Claim Type:	If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	2409		
Damage Code:	0039		
Labor Operations:	GFF / Guided Functions	0150 0010	See SRT with associated operations
	GFF / Guided Functions	0150 0060	Labor according to the diagnostic log
Claim Comment:	As per TSB 2083125/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Please note the information on predecessors and items that are included and excluded in the repair operations, as well as any associated tasks.

Additional Information

All part and service references provided in this TSB (**2083125**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, LLC / Audi Canada Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, LLC / Audi Canada Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.