

2025 Plateau

COMPLAINT - CUSTOMER STATES THAT THE WATER PUMP RUNS CONSTANTLY

CAUSE - WATER PUMP DIAPHRAGM FAILED INTERNALLY, REMOVED DRAWER, CAPPED WATER PUMP AND TESTED PRESSURE. DIAPHRAGM NOT BUILDING PRESSURE.

CORRECTION - NEED AUTH TO REPLACE WATER PUMP

1.1.0HRS 0.50 approved.