

2027 Ontour

Complaint:

LP FILL HOSE IS LEAKING AND WILL NOT HOLD PRESSURE

Cause:

PREFORMED PDI AND FOUND THE LP HOSE HAS AN INTERNAL FAILURE. THE HOSE WILL NOT SEAL PROPERLY CAUSING AN LP LEAK.

Correction:

REMOVE AND REPLACE THE DEFECTIVE LP FILL HOSE. AFTER REPLACEMENT PRESSURE TEST THE LP SYSTEM VERIFY THE ARE NO LEAKS AND CONFIRM SYSTEM OPERATES AS DESIGN.