

2026 Ontour

- B) p: owner states when removing the discharge tube cap get black tank liquid
c: bad valve
r: verified complaint changed it and tested.

Line1- 0.5 approve R&R gate valve.

2026 Ontour

2. CUSTOMER STATES THAT THERE IS A LEAK AT THE BLACK TANK VALVE AREA. FLUID IS DRIPPING BETWEEN THE TANK AND THE VALVE. BLACK TANK VALVE LEAKING NEED TO REPLACE, LABOR TO R/R NEW BRISTOL SEWER BLACK VALVE. 1.8HR REPLACEMENT VALVE IN STOCK
0.70 approved maximum. There are only 4 screws for the gate valve, separate the pipe and insert the new gate valve.