



Radio Over The Air Update to U43.17 R1H Software
Version (FOTA)

9/8/2026

VEHICLES
AFFECTED:

2026 (VF) RAM Promaster

UCONNECT 5 NAV W 10.1" DISPLAY (CAN) (Sales Code UEN)

UCONNECT 5 NAV W 10.1" DISPLAY (USA) (Sales Code UBN)

MARKET APPLICABILITY:

☒ NA

☐ MEA

☐ SA

☐ IAP

☐ EE

☐ CH

CUSTOMER
SYMPTOM:

Customers may experience one or more of the following:

- Navigation Stability
- Android Auto & Carplay stability & connectivity
- Distorted/glitchy display prior to start-up animation
- Text appearance display
- Widget incorrect display
- Turn signal blind spot response timing
- Audio cut out
- Drive Modes selection
- Park assist Guidelines selection