



Radio Over The Air Update to U43.17 R1H Software
Version (FOTA)

9/8/2026

**VEHICLES
AFFECTED:**

2026 - 2027 (DT) RAM 1500 Pickup

UCONNECT 5 NAV W 12.0" DISPLAY (CAN) (Sales Code UEQ)
UCONNECT 5 NAV W 12.0" DISPLAY (USA) (Sales Code UBQ)
UCONNECT 5 NAV W 14.4" Display (CAN) (Sales Code UEW)
UCONNECT 5 NAV W 14.4" Display (USA) (Sales Code UBW)

MARKET APPLICABILITY:

☒ NA	☐ MEA
☐ SA	☐ IAP
☐ EE	☐ CH

**CUSTOMER
SYMPTOM:**

Customers may experience one or more of the following:

- Navigation Stability
- Android Auto & Carplay stability & connectivity
- Air suspension
- Trailer Tow pages
- Power management app
- Distorted/glitchy display prior to start-up animation
- Text appearance display
- Widget incorrect display
- Turn signal blind spot response timing
- Audio cut out
- Drive Modes selection
- Park assist Guidelines selction