

Technical Bulletin

FROM: Maserati TSO

TO: Maserati Network



PERSONAL SERVICE LAB

MASTERS OF CARE

GranTurismo and GranCabrio - Unexpected Alarm Activation

DATE: Sept 10, 2026

In case of unexpected alarm activation, proceed with software updates to the BCM ECU, with Software Number F188 670363089 ROW.

In order to obtain the compatibility of this SW and to complete all the necessary steps and procedures with MDEVO, it is mandatory to open a BOL as Support Request.

After updating the software to the version mentioned above, perform the BCM procedure 'BCM Initialization'.

MODELS AFFECTED: GranTurismo and GranCabrio, all versions with Premium Alarm system (OPT+213).

Warranty Claim Information

For the operations described in this publication, only the operations listed here will be approved under warranty. Any additional requests will be rectified.

Description	Code
Component Code	8.61.035
Bulletin Topic	8.61.035F (0,30 h)

We remain at your disposal for clarifications.

Best regards,

TECHNICAL SERVICE OPERATIONS