



## **SSM 55186 2026 Explorer - Wind Noise And/Or Water Intrusion From Panoramic Roof Panel Glass Seal**

Some 2026 Explorer vehicles may exhibit wind noise and/or water intrusion from the panoramic roof panel glass seal. Inspection may find that the seal is rolled or separated from the glass. The seal is not serviceable separately from the glass. To correct this condition, replace the panoramic roof panel glass assembly. Refer to Workshop Manual, Section 501-11 > Removal and Installation > Panoramic Roof Panel Glass. For claiming, use causal part 78500A18 and labor operation 50282BG.