

	SERVICE BULLETIN	Issue no.	RE-IB-SB-101
		Issue date	07 th Sept 2026
		Page No	Page 1 of 2
SUBJECT	MODIFICATION ON CLUTCH CABLE ASSEMBLY		
APPLICABLE MODELS	SUPER METEOR 650		

This Service Bulletin is to inform about the modification done in the clutch cable assembly.

Reason: Continuous improvement

Modification: Inner cable material change from Galvanized steel to Stainless steel

Before Modification	After Modification
 Galvanized with nylon coated	 Stainless steel with nylon coated

Parts Details and Interchangeability Information

SI #	Part Description	Models	Action			Qty .	Inter changeable	Remarks
			Addition	Deletion	Modification			
1	CLUTCH CABLE ASSY	Super Meteor 650		RAL01050/C	RAL01050/D		Y	

Vehicle Cut-Off Details:

ZONE	FRAME NUMBERS	ENGINE NUMBER	MODEL
EUROPE	ME3CNEST6SK001696	P7A6FAS1007009	SUPER METEOR 650
APAC	ME3CNEST6SK001710	P7A6FAS1007232	SUPER METEOR 650
LATAM	ME3CNEST6SK001689	P7A6FAS1007050	SUPER METEOR 650
MEA	Shall be announced separately through email		SUPER METEOR 650
NORTH AMERICA	ME3HJN479TK700072	P7A6FAT1016987	SUPER METEOR 650
BRAZIL	95V6L1E2TTM002809	P7A6FETA017447	SUPER METEOR 650
ARGENTINA	Shall be announced separately through email		SUPER METEOR 650
COLOMBIA	Shall be announced separately through email		SUPER METEOR 650
THAILAND	Shall be announced separately through email		SUPER METEOR 650

Royal Enfield (A Unit of Eicher Motors Ltd.)

Thiruvottiyur High Road | Thiruvottiyur | Chennai - 600019 | Tamil Nadu | India

	SERVICE BULLETIN	Issue no.	RE-IB-SB-101
		Issue date	07 th Sept 2026
		Page No	Page 2 of 2
SUBJECT	MODIFICATION ON CLUTCH CABLE ASSEMBLY		
APPLICABLE MODELS	SUPER METEOR 650		

Action Required:

- No action required on customer motorcycles and stock motorcycles.
- No action is required for the existing parts in the stock

Applicable Countries: All countries, except SAARC countries

Please update your Spare Parts master and request to share this information to all the concerned.

