

GM CUSTOMER CARE AND AFTERSALES
DCS3915
URGENT - DISTRIBUTE IMMEDIATELY

Date: February 1, 2016

Subject: 04014D – Safety Recall
Engine Fuel Rail - Replace
Revised Service Procedure section

Models: 1995-1997 Cadillac DeVille Concours, Seville, Eldorado
1996-1997 Cadillac DeVille
Equipped with 4.6L V8 (RPO LD8 – VIN Y; RPO L37 – VIN 9) Engine
1995-1997 Oldsmobile Aurora
Equipped with 4.0L V8 (RPO L47 – VIN C) Engine

To: All General Motors Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, Used Vehicle Sales Manager,
and Warranty Administrator

This bulletin was revised to add two pictures to Step 2 in the Inspection Procedure, and one picture to Step 24 in the 1995 Oldsmobile Aurora Fuel Chassis Line Removal and Installation procedure within the Service Procedure section. Please discard all copies of bulletin 04014C.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES