

Attachment IV

Customer Satisfaction Program 12B40 - Certain 2013 Model Year Taurus, MKS and MKT Vehicles equipped with the
Blind Spot Information System - Side Obstacle Detection Module Replacement

Use the following chart to identify suspect VINs and Side Obstacle Detection (SOD) Modules to be replaced:

In Adobe Reader menu, click "**EDIT**", then click "**FIND**", then insert the complete VIN or the last 6 characters, then press "**ENTER**".

OR

Press "**CTRL**" and "**F**" simultaneously, then insert the complete VIN or the last 6 characters, then press "**ENTER**".

Taurus		
VIN	LEFT	RIGHT
1FAHP2F80DG133285	X	
1FAHP2F80DG134176	X	
1FAHP2F80DG134341	X	
1FAHP2F80DG135666		X
1FAHP2F81DG134087	X	
1FAHP2F81DG134185	X	
1FAHP2F81DG134199	X	
1FAHP2F81DG134204		X
1FAHP2F81DG134378	X	
1FAHP2F81DG135966	X	X
1FAHP2F81DG136230	X	X
1FAHP2F82DG134213	X	
1FAHP2F82DG134308		X
1FAHP2F82DG135667		X
1FAHP2F82DG136060		X
1FAHP2F83DG133605	X	
1FAHP2F83DG134088	X	
1FAHP2F83DG134107	X	
1FAHP2F83DG134348	X	
1FAHP2F83DG135824	X	X
1FAHP2F83DG136245	X	
1FAHP2F84DG133256	X	
1FAHP2F84DG133368	X	
1FAHP2F84DG134343	X	
1FAHP2F84DG135797		X
1FAHP2F85DG134089	X	
1FAHP2F85DG134304		X
1FAHP2F85DG134349	X	
1FAHP2F85DG134397	X	
1FAHP2F85DG134402	X	
1FAHP2F85DG135615		X
1FAHP2F85DG135713	X	

VIN	LEFT	RIGHT
1FAHP2F85DG135730	X	
1FAHP2F85DG135954	X	X
1FAHP2F85DG136036		X
1FAHP2F86DG133520	X	
1FAHP2F86DG134179	X	
1FAHP2F86DG134408		X
1FAHP2F86DG134442	X	
1FAHP2F86DG135817		X
1FAHP2F86DG135980	X	
1FAHP2F86DG136028		X
1FAHP2F87DG133333	X	
1FAHP2F87DG134109	X	
1FAHP2F87DG134191	X	
1FAHP2F87DG135728	X	X
1FAHP2F87DG135759		X
1FAHP2F87DG135955		X
1FAHP2F87DG136393	X	
1FAHP2F88DG134345	X	
1FAHP2F88DG134376	X	
1FAHP2F88DG135706	X	
1FAHP2F88DG136144	X	X
1FAHP2F88DG136158	X	X
1FAHP2F88DG136287		X
1FAHP2F89DG134452	X	
1FAHP2F89DG135942		X
1FAHP2F8XDG134346	X	
1FAHP2F8XDG134380	X	
1FAHP2F8XDG135738	X	
1FAHP2F8XDG136128		X
1FAHP2J81DG136008	X	X
1FAHP2J82DG135594		X
1FAHP2J84DG135144	X	X

VIN	LEFT	RIGHT
1FAHP2J84DG135158		X
1FAHP2J85DG135153		X
1FAHP2J88DG136345	X	X
1FAHP2J89DG135575	X	X
1FAHP2KT0DG133121		X
1FAHP2KT0DG133488	X	
1FAHP2KT0DG133717		X
1FAHP2KT0DG135774		X
1FAHP2KT1DG133189		X
1FAHP2KT2DG133119		X
1FAHP2KT2DG133122		X
1FAHP2KT2DG133637	X	
1FAHP2KT3DG133372		X
1FAHP2KT3DG135557	X	
1FAHP2KT4DG136250		X
1FAHP2KT6DG133611		X
1FAHP2KT7DG133178		X
1FAHP2KT7DG133343	X	
1FAHP2KT7DG135531	X	
1FAHP2KT7DG135593	X	X
1FAHP2KT7DG136162		X
1FAHP2KT8DG133769	X	
1FAHP2KT8DG135540	X	
1FAHP2KT9DG135739		X
1FAHP2KT9DG135773		X
1FAHP2KTXDG135572	X	X
1FAHP2M87DG132539		X

Attachment IV

Customer Satisfaction Program 12B40 - Certain 2013 Model Year Taurus, MKS and MKT Vehicles equipped with the Blind Spot Information System - Side Obstacle Detection Module Replacement

Use the following chart to identify suspect VINs and Side Obstacle Detection (SOD) Modules to be replaced:

In Adobe Reader menu, click "**EDIT**", then click "**FIND**", then insert the complete VIN or the last 6 characters, then press "**ENTER**".

OR

Press "**CTRL**" and "**F**" simultaneously, then insert the complete VIN or the last 6 characters, then press "**ENTER**".

MKS		
VIN	LEFT	RIGHT
1LNHL9DK0DG605753	X	
1LNHL9DK0DG605882	X	
1LNHL9DK0DG605915	X	
1LNHL9DK0DG606174	X	
1LNHL9DK0DG606207	X	
1LNHL9DK1DG605745		X
1LNHL9DK1DG606152	X	
1LNHL9DK1DG606202	X	
1LNHL9DK1DG606216	X	
1LNHL9DK2DG605706	X	
1LNHL9DK3DG605746		X
1LNHL9DK3DG606198	X	
1LNHL9DK4DG605707	X	
1LNHL9DK4DG605982	X	
1LNHL9DK4DG606159	X	
1LNHL9DK5DG605747		X
1LNHL9DK5DG605750		X
1LNHL9DK5DG605943	X	
1LNHL9DK5DG605991	X	
1LNHL9DK5DG606137	X	
1LNHL9DK6DG605899	X	
1LNHL9DK6DG605949	X	
1LNHL9DK6DG606129	X	
1LNHL9DK6DG606132	X	
1LNHL9DK7DG605698	X	
1LNHL9DK7DG605930	X	
1LNHL9DK7DG606091	X	
1LNHL9DK7DG606169	X	
1LNHL9DK8DG605712	X	
1LNHL9DK8DG605757	X	
1LNHL9DK8DG605760	X	
1LNHL9DK8DG605922	X	
1LNHL9DK8DG606116		X

VIN	LEFT	RIGHT
1LNHL9DK8DG606150	X	
1LNHL9DK8DG606181	X	
1LNHL9DK8DG606200	X	
1LNHL9DK9DG605699	X	
1LNHL9DK9DG605749		X
1LNHL9DK9DG605914	X	
1LNHL9DK9DG605945	X	
1LNHL9DKXDG605890	X	
1LNHL9DKXDG605923	X	
1LNHL9EK1DG605839	X	
1LNHL9EK2DG605820	X	
1LNHL9EK3DG605776		X
1LNHL9EK3DG606068	X	
1LNHL9EK5DG605830	X	
1LNHL9EK6DG605867	X	
1LNHL9EK8DG605806		X
1LNHL9EK8DG605837		X
1LNHL9EK8DG606051		X
1LNHL9EK9DG606107	X	X
1LNHL9EK9DG606110		X
1LNHL9EKXDG605824		X
1LNHL9EKXDG606052		X
1LNHL9FT1DG605704	X	
1LNHL9FT1DG605928		X
1LNHL9FT2DG605792		X
1LNHL9FT2DG606084	X	
1LNHL9FT3DG606031		X
1LNHL9FT4DG605793	X	
1LNHL9FT4DG606037		X
1LNHL9FT4DG606085	X	
1LNHL9FT5DG606032		X
1LNHL9FT5DG606046	X	X
1LNHL9FT7DG605805	X	

VIN	LEFT	RIGHT
1LNHL9FT7DG605822		X
1LNHL9FT7DG606100		X
1LNHL9FT7DG606162	X	
1LNHL9FT8DG605862		X
MKT		
VIN	LEFT	RIGHT
2LMHJ5AT1DBL52398	X	
2LMHJ5AT7DBL52339	X	
2LMHJ5AT7DBL52342	X	
2LMHJ5NK1DBL52435	X	
2LMHJ5NK9DBL52425	X	
2LMHJ5NK3DBL52436	X	