## GM CUSTOMER CARE AND AFTERSALES DCS 3325 URGENT - DISTRIBUTE IMMEDIATELY

| Date:      | September 3, 2014  |
|------------|--|
|            |  |
| Subject:   | Upcoming Safety Recall – 14093                               |
|            | DRL Module/Headlamp Switch May Overheat                      |
| NAI - I    | 0004 0000 01   |
| Models:    | 2004-2008 Chevrolet Aveo                                     |
|            | 2005-2008 Pontiac G3 / Wave (Canada Only)                    |
|            | 2004-2006 Chevrolet Epica (Canada Only)                      |
|            | 2004-2007 Chevrolet Optra (Canada Only)                      |
| То:        | All GM Dealers   |
| 10.        | y III CIVI Dodioio   |
| Attention: | General Manager, Service Advisor, Service Manager, Parts and |
|            | Service Director, Parts Manager, New Vehicle Sales Manager,  |

General Motors has notified the National Highway Traffic Safety Administration (NHTSA) about an upcoming safety recall that involves 2004-2008 model year (MY) Chevrolet Aveo, 2005-08 (MY) Pontiac G3 / Wave (Canada), 2004-2006 (MY) Chevrolet Epica (Canada) and 2004-2007 Chevrolet Optra (Canada) vehicles. The GM recall number is 14093.

Heat generated within the headlamp switch, or daytime running lamp (DRL) module, which are both located on or near the left side of the steering column could melt the headlamp switch or DRL module and cause a fire.

This is a courtesy notification to dealers. We are working as quickly as possible to correct this condition. Dealers will be advised when a repair and parts are scheduled for release.

The Investigate Vehicle History screen in the Global Warranty Management system has been updated for this upcoming safety recall. This action has been taken to assist dealers with determining which vehicles are involved so they can properly respond to customer inquiries. Please note the "N/A" under Release Date and the "Incomplete – Remedy not yet available" message under Status. This means release of the recall bulletin is still pending and dealers should not attempt to perform any repairs at this time.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES