OMB Control No.: 2127-0004

Part 573 Safety Recall Report

14V-763

Manufacturer Name: Subaru of America, Inc.

Submission Date : JAN 14,2015 **NHTSA Recall No. :** 14V-763

Manufacturer Recall No.: WQP-51



Manufacturer Information:

Manufacturer Name: Subaru of America, Inc.

Address: P.O. Box 6000

Cherry Hill NJ 08034-6000 Company phone : 856-488-8500

Population:

Number of potentially involved: 10,202 Estimated percentage with defect: 0

Vehicle Information:

Vehicle: 2003-2003 Subaru Legacy Vehicle Type: LIGHT VEHICLES

Body Style : 4-DOOR Power Train : GAS

Descriptive Information: Information Regarding Manufacturer of Defective Component: • Identification of

Component: Front passenger airbag inflator • Component Manufacturer: TK Holdings, Inc. • Address: 888 16th Street NW – Suite 800 Washington, DC 20006 •

Phone Number: (202)729-6332 • Component's Country of Origin: Mexico

Production Dates: FEB 18, 2003 - JUN 06, 2003

VIN (Vehicle Identification Number) Range

Begin: NR End: NR Not sequential VINs

Vehicle: 2004-2004 Subaru Legacy Vehicle Type: LIGHT VEHICLES

Body Style : 4-DOOR Power Train : GAS

Descriptive Information : Information Regarding Manufacturer of Defective Component: • Identification of

Component: Front passenger airbag inflator • Component Manufacturer: TK Holdings, Inc. • Address: 888 16th Street NW – Suite 800 Washington, DC 20006 •

Phone Number: (202)729-6332 • Component's Country of Origin: Mexico

Production Dates: MAR 17, 2003 - MAR 01, 2004

VIN (Vehicle Identification Number) Range

Vehicle: 2005-2005 Subaru Legacy Vehicle Type: LIGHT VEHICLES

Body Style : 4-DOOR Power Train : GAS Descriptive Information	: Information Regarding Manufacturer of Defective Component: Front passenger airbag inflator • Con Haldings Inc. Address: 888 16th Street NW Sv	mponent Manufacturer: TK				
	Holdings, Inc. • Address: 888 16th Street NW – Su Phone Number: (202)729-6332 • Component's Co	S .				
Production Dates : FEB 2	-					
VIN (Vehicle Identification Number) Range						
Begin: NR	End : NR	☐ Not sequential VINs				
Vehicle: 2003-2003 Sul Vehicle Type: LIGHT VE Body Style: SUV Power Train: GAS						
Descriptive Information : Information Regarding Manufacturer of Defective Component: • Identification of Component: Front passenger airbag inflator • Component Manufacturer: TK Holdings, Inc. • Address: 888 16th Street NW – Suite 800 Washington, DC 20006 • Phone Number: (202)729-6332 • Component's Country of Origin: Mexico Production Dates: FEB 18, 2003 - JUN 11, 2003						
VIN (Vehicle Identifica	· ·					
Begin : NR	End : NR	☐ Not sequential VINs				
Vehicle: 2004-2004 Sul Vehicle Type: LIGHT VE Body Style: SUV Power Train: GAS						
	: Information Regarding Manufacturer of Defective	e Component: • Identification of				
Component: Front passenger airbag inflator • Component Manufacturer: TK Holdings, Inc. • Address: 888 16th Street NW – Suite 800 Washington, DC 20006 • Phone Number: (202)729-6332 • Component's Country of Origin: Mexico						
Production Dates : MAR	13, 2003 - MAR 15, 2004					
VIN (Vehicle Identification Number) Range						
Begin : NR	End : NR	☐ Not sequential VINs				
Vehicle: 2005-2005 Sul Vehicle Type: LIGHT VE Body Style: SUV Power Train: GAS						
Descriptive Information : Information Regarding Manufacturer of Defective Component: • Identification of Component: Front passenger airbag inflator • Component Manufacturer: TK Holdings, Inc. • Address: 888 16th Street NW – Suite 800 Washington, DC 20006 • Phone Number: (202)729-6332 • Component's Country of Origin: Mexico						

Production Dates : FEB 06, 2004 - OCT 06, 2004					
VIN (Vehicle Identifica	VIN (Vehicle Identification Number) Range				
Begin : NR	End : NR	☐ Not sequential VINs			
Vehicle: 2003-2003 Su Vehicle Type: LIGHT VE Body Style: SUV Power Train: GAS Descriptive Information	•	Component Manufacturer: TK			
Production Dates : FEB	Phone Number: (202)729-6332 • Component's				
VIN (Vehicle Identifica	tion Number) Range				
Begin : NR	End : NR	☐ Not sequential VINs			
Vehicle: 2004-2004 Subaru Baja Vehicle Type: LIGHT VEHICLES Body Style: SUV Power Train: GAS Descriptive Information: Information Regarding Manufacturer of Defective Component: • Identification of Component: Front passenger airbag inflator • Component Manufacturer: TK Holdings, Inc. • Address: 888 16th Street NW – Suite 800 Washington, DC 20006 • Phone Number: (202)729-6332 • Component's Country of Origin: Mexico Production Dates: APR 07, 2003 - JUL 21, 2004					
VIN (Vehicle Identifica	tion Number) Range				
Begin : NR	End : NR	☐ Not sequential VINs			
Vehicle: 2005-2005 Subaru Baja Vehicle Type: LIGHT VEHICLES Body Style: SUV Power Train: GAS Descriptive Information: Information Regarding Manufacturer of Defective Component: • Identification of Component: Front passenger airbag inflator • Component Manufacturer: TK Holdings, Inc. • Address: 888 16th Street NW – Suite 800 Washington, DC 20006 • Phone Number: (202)729-6332 • Component's Country of Origin: Mexico Production Dates: MAR 16, 2004 - OCT 27, 2004					
VIN (Vehicle Identifica	tion Number) Range				
Begin : NR	End : NR	☐ Not sequential VINs			

Vehicle: 2004-2004 Sul	paru Impreza					
Vehicle Type : LIGHT VE	•					
Body Style : 4-DOOR						
Power Train : GAS						
Descriptive Information	: Information Regarding Manufacturer of Defective Cor	nponent: • Identification of				
	Component: Front passenger airbag inflator • Component Manufacturer: Takata Corporation • Address: ARK Hills South Tower 11F 4-5 Roppongi 1-Chone, Minatoku, Tokyo 106-8488 Japan • Phone Number: +81-3-3582-3222 • Component's Country of Origin: Mexico					
Production Dates : JAN 2						
VIN (Vehicle Identifica	tion Number) Range					
Begin: NR	End : NR	☐ Not sequential VINs				
Vehicle: 2004-2004 Subaru Impreza Vehicle Type: LIGHT VEHICLES Body Style: STATIONWAGON Power Train: GAS Descriptive Information: Information Regarding Manufacturer of Defective Component: • Identification of Component: Front passenger airbag inflator • Component Manufacturer: Takata Corporation • Address: ARK Hills South Tower 11F 4-5 Roppongi 1-Chone, Minatoku, Tokyo 106-8488 Japan • Phone Number: +81-3-3582-3222 •						
Production Dates : JAN 2	Component's Country of Origin: Mexico Production Dates : JAN 28, 2003 - FEB 13, 2004					
VIN (Vehicle Identifica	tion Number) Range					
Begin: NR	End : NR	☐ Not sequential VINs				
Vehicle: 2005-2005 Subaru Impreza Vehicle Type: LIGHT VEHICLES Body Style: 4-DOOR Power Train: GAS Descriptive Information: Information Regarding Manufacturer of Defective Component: • Identification of Component: Front passenger airbag inflator • Component Manufacturer: Takata Corporation • Address: ARK Hills South Tower 11F 4-5 Roppongi 1-Chone, Minatoku, Tokyo 106-8488 Japan • Phone Number: +81-3-3582-3222 • Component's Country of Origin: Mexico Production Dates: FEB 16, 2004 - DEC 10, 2004						
VIN (Vehicle Identification Number) Range						
Begin : NR	End : NR	☐ Not sequential VINs				
Vehicle: 2005-2005 Subaru Impreza Vehicle Type: LIGHT VEHICLES Body Style: STATIONWAGON						

Power Train: GAS

Descriptive Information: Information Regarding Manufacturer of Defective Component: • Identification of

Component: Front passenger airbag inflator • Component Manufacturer: Takata Corporation • Address: ARK Hills South Tower 11F 4-5 Roppongi 1-Chone, Minatoku, Tokyo 106-8488 Japan • Phone Number: +81-3-3582-3222 •

Component's Country of Origin: Mexico

Production Dates: FEB 11, 2004 - DEC 10, 2004

VIN (Vehicle Identification Number) Range

Begin: NR End: NR Not sequential VINs

Vehicle: 2005-2005 Saab 9-2X Vehicle Type: LIGHT VEHICLES Body Style: STATIONWAGON

Power Train: GAS

Descriptive Information: Information Regarding Manufacturer of Defective Component: • Identification of

Component: Front passenger airbag inflator • Component Manufacturer: Takata Corporation • Address: ARK Hills South Tower 11F 4-5 Roppongi 1-Chone, Minatoku, Tokyo 106-8488 Japan • Phone Number: +81-3-3582-3222 •

Component's Country of Origin: Mexico

Production Dates: FEB 11, 2004 - OCT 27, 2004

VIN (Vehicle Identification Number) Range

Begin: NR End: NR Not sequential VINs

Description of Defect:

Description of the Defect: Subaru of America, Inc. (Subaru) is conducting a recall of certain model year

2003-2005MY Subaru Legacy, Outback, and Baja vehicles, certain 2004-2005MY Subaru Impreza (including WRX/STI) vehicles and certain 2005MY Saab 9-2X vehicles, that are currently or have ever been registered in the following areas of high absolute humidity: Hawaii, Florida and counties adjacent to it in Southern Georgia, as well as the coastal areas of Alabama, Louisiana, Mississippi and Texas as well as Puerto Rico, the U.S. Virgin Islands, Guam, Saipan, and American Samoa. The air bag inflators in the front passenger air bags for these vehicles could be susceptible to rupture and the front passenger air bag could deploy abnormally in a crash. The cause of the potential for ruptured inflators and the influence of high

absolute humidity are under investigation.

Description of the Safety Risk : In the event of a crash necessitating deployment of the passenger side frontal air bag, the inflator could rupture with metal fragments striking and potentially

seriously injuring the vehicle occupants.

Description of the Cause: NR

Identification of Any Warning that can Occur: NR

Supplier Identification:

Component Manufacturer

Name: NR Address: NR

FOREIGN STATES

Country: NR

Chronology:

July 3, 2014: Subaru submitted Part 573 Safety Recall Report for a known safety defect related to improperly manufactured propellant wafers used in certain front passenger airbag inflators (NHTSA Recall No. 14V-399; Subaru No. WQL-48).

August 19, 2014: Subaru notified NHTSA it was initiating a voluntary, regional parts collection campaign to cooperate with NHTSA and the Supplier's (TK Holdings, Inc./Takata) ongoing investigation of the risk of failure of the passenger airbag inflators installed on certain vehicles that are currently or have ever been registered in Florida, Hawaii, Puerto Rico, and the U.S. Virgin Islands (NHTSA Recall No. 14V-471; Subaru No. WQM-49).

November 10, 2014: Takata submitted a Part 573 Safety Recall Report (NHTSA Recall No. 14E-073)

November 21, 2014: NHTSA suggested that Subaru consider moving from a voluntary campaign (NHTSA Recall No. 14V-471; Subaru No. WQM-49) to a Part 573 safety recall as well as expanding the geographic coverage.

November 25-26, 2014: NHTSA and Subaru had follow-up discussions regarding the information shared on November 21, 2014.

November 27, 2014: FHI concluded that Subaru will move from a voluntary campaign (NHTSA Recall No. 14V-471; Subaru No. WQM-49) to a Part 573 safety recall as well as expanding the geographic coverage.

Description of Remedy:

Description of Remedy Program: The remedy plan calls for dealers to replace the passenger airbag inflator with a newly manufactured one.

How Remedy Component Differs from Recalled Component: NR

Identify How/When Recall Condition was Corrected in Production: NR

Recall Schedule:

Description of Recall Schedule: NR

Planned Dealer Notification Date: NR - NR

Planned Owner Notification Date: NR - NR

Part 573 Safety R	ecall Report	14V-763	Page 7
* NR - Not Reported			
	The information contained in this re	port was submitted pursuant to 49 CFR §573	