

Michael A. Berardi Director Service Engineering Operations Ford Customer Service Division Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

June 4, 2015

TO: All U.S. Ford and Lincoln Dealers

SUBJECT: DEMONSTRATION / DELIVERY HOLD - Advance Notice - Safety Recall 15S21 -

Supplement #1

Certain 2005-2006 Ford GT and 2005-2014 Mustang Vehicles

Driver Airbag Inflator Replacement

AFFECTED VEHICLES

Vehicle	Model Year	Assembly Plant	Build Dates
Ford GT	2005-2006	Wixom	February 20, 2004 through September 22, 2006
Mustang	2005-2014	Flatrock	April 6, 2004 through June 21, 2014

Affected vehicles are identified in OASIS. In addition, for a list of vehicles assigned to your dealership, visit https://web.fsavinlists.dealerconnection.com.

REASON FOR THIS SAFETY RECALL

Takata has determined that the air bag inflator propellant wafers in some inflators may experience an alteration over time, which could potentially lead to an over-aggressive combustion in the event of an airbag deployment. This potential condition could create excessive internal pressure when the airbag is deployed, which could result in the body of the inflator rupturing upon deployment increasing the risk of injury to occupants.

New! <u>SERVICE</u> ACTION

A complete Dealer Bulletin will be provided to dealers when parts ordering information and repair instructions will be available to support this safety recall.

NOTE: Some vehicles included in 15S21 are also included in 14B09. The repair parts for 15S21 have not yet been developed and will be the subject of a future announcement.

- Vehicles that are currently open in 14B09 and 15S21 Dealers should replace the driver airbag inflator under 14B09.
- Vehicles that are open in 15S21 Repairs will be the subject of a future announcement.

New! CUSTOMER NOTIFICATION

Owners of record will be notified via first-class mail the week of July 13, 2015 that parts are not currently available under 15S21. Customers will be re-notified after repair instructions and parts ordering information are provided to dealers.

PLEASE NOTE:

Federal law requires dealers to complete this recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to \$7,000 per vehicle. Correct all vehicles in your new vehicle inventory prior to delivery

QUESTIONS

Special Service Support Center (Dealer Assistance Only) ______1-800-325-5621

Sincerely,

Michael A. Berardi