 15240B - Safety Recall - Power Lift Gate Prop Rod Recovery - Part Information Section Revised
Updated Date: Mar 16, 2016 16:00 ET

GM CUSTOMER CARE AND AFTERSALES
DCS3967
URGENT - DISTRIBUTE IMMEDIATELY

Date: March 16, 2016

Subject: 15240B - Safety Recall
Power Lift Gate Prop Rod Recovery
Part Information Section Revised


Models: 2007-2010 Saturn Outlook
2007-2012 GMC Acadia
2009-2012 Chevrolet Traverse
2008-2012 Buick Enclave
Equipped with Power Lift Gate Option (RPO TB5 or E61) and
Built Prior to March 1, 2012

To: All General Motors Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, Used Vehicle Sales Manager,
and Warranty Administrator

The Part Information section has been revised because the usage for part number 22918205 has been changed to manual lift gate only. Effective immediately, part number 22918205 should no longer be used for this recall. In its place, use part number 84050727, which is a new design right lift gate strut for the Acadia and Outlook. Vehicles previously repaired with part number 22918205 are satisfactory and require no further action. Please see the attached bulletin for details and discard all copies of bulletin 15240A.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES

 15240B Bulletin.pdf

About this Alert

Reference Number: GCUS-3-473
Published to: Home Page
Version: 1.0
Alert Type: Product Safety
Original Published Date: Mar 16, 2016 16:00 ET
Expires: May 15, 2016 0:00 ET
Contact : loren.rusk@gm.com