## OMB Control No.: 2127-0004

## **Recall Quarterly Report**

16V-738

**Manufacturer Name:** Subaru of America, Inc.

NHTSA Recall No. / MFR Recall No.: 16V-738 /WTM-73

**Recall Subject:** Power Relay may Fail Allowing Air Pump to Overheat

**Owner Notification Beginning Date :** DEC 16, 2016

Owner Notification End Date: DEC 16, 2016



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
5	JAN 08, 2018	2017-4	100,127	55,512	3,801	0
4	OCT 06, 2017	2017-3	100,127	49,674	3,801	0
3	JUL 14, 2017	2017-2	100,127	44,092	3,801	0
2	APR 12, 2017	2017-1	100,127	36,259	0	0
1	JAN 23, 2017	2016-4	100,127	15,807	0	0

This Document Last Updated: JAN 09, 2018

## **Definitions:**

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the  $3^{rd}$  quarter of 2012). Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.