



MERCEDES-BENZ USA, LLC 303 Perimeter Center North, Suite 202 Atlanta, GA, 30346 Phone: (770) 705-0600 Fax: (770) 705-0117

## newschannel update

то: Mercedes-Benz Dealer Principals, General	FROM: Thomas Brunner, Department Manager,
Managers, Sales Managers, Service Managers, Parts	Vehicle Compliance and Analysis, Engineering
Managers	Services
RE: Recall Campaign 2016120005	
MY 2017 Model 207(E-Coupe)	DATE: December 22, 2016
Replace Electric Power Steering ECU	

## **IMPORTANT NEW RECALL INFORMATION**

Please see the attached document for the subject new recall campaign.







## NEW RECALL CAMPAIGN NOTIFICATION

Campaign No.:	
2016120005	

## **Electric Power Steering ECU Replacement**

This is to notify you of a new **Recall Campaign** to replace the Electric Power Steering Electronic Control Unit on **70** MY2017 E-Class Coupe (207 platform) vehicles. <u>Please review the recall information below</u>. All affected VINs are flagged in VMI as "Pending". We are working to launch the recall in early February when parts become available. This recall will be posted to the NHTSA <a href="https://www.safercar.gov">www.safercar.gov</a> website shortly and may generate questions from customers or media. Customer inquiries should be directed to the CAC. Media inquiries should be directed to the MBUSA PR department.

	irected to the MBUSA PR department. ext NCU is posted and the recall is launched.
There is no action required until the h	
Background	
Issue	Daimler AG ('DAG') the manufacturer of Mercedes-Benz vehicles has become aware that certain E-Class Coupe (207 platform) vehicles might have been built with electric power steering control units that were equipped with improperly soldered contacts. If the affected pins lose complete electrical contact, the vehicle's electric power steering may deactivate, increasing the risk of a crash. In addition, the complete loss of electrical contact could lead to a short circuit within the control unit, increasing the risk of a fire.
What We're Doing	MBUSA will conduct a voluntary recall when parts become available in Early February. An authorized Mercedes-Benz dealer will replace the control unit on the affected vehicles.
Parts	Parts are not yet available, and will likely become available in early February, 2017.
Vehicles Affected	
Vehicle Model Year	2017
Vehicle Models	E-Class Coupe (207 platform)
Vehicle Populations	
Total Recall Population	70
<b>Total Vehicles in Dealer Inventory</b>	0
Dealer Notification (NCU)	
Documentation pertaining to this recall will be received by dealers in NetStar and Star TekInfo on the following date:	December 22, 2016
Next Steps/Notes	
Owner notification letter timeline	Customer <b>interim</b> notification letters will be mailed in early January 2017, informing them that parts are not yet available. We are working to obtain the necessary parts to correct this condition as quickly as possible. As parts become available, we will send owners another letter asking them to take their vehicle to an authorized Mercedes-Benz dealer to have the issue corrected free of charge.  Customers may continue to drive their vehicles until parts become available.
AOMS/SOMS	AOMs - Please make sure your dealers read and understand the details of this recall.

While we regret any inconvenience this may cause, MBUSA is determined to maintain a high level of vehicle quality and customer satisfaction. Please refer all customer inquiries to the Customer Assistance Center at 1-800-FOR-MERCEDES. Please contact Allen Ambulo (x2579) or me with any questions.