

## **CERTAIN 2017 MODEL YEAR CONTINENTAL AND 2016-2017 MODEL YEAR EDGE AND MKX VEHICLES — DRIVER AIRBAG MODULE REPLACEMENT**

### **OVERVIEW**

Some of the affected vehicles may not conform to the requirements specified by Federal Motor Vehicle Safety Standard (FMVSS) No. 208, Occupant Crash Protection. In the event of a driver airbag deployment, the driver airbag cushion may not completely fill, or the cushion may detach from the airbag module, increasing risk of an injury to the driver in a crash. Dealers are to replace the driver airbag module.

### **SERVICE PROCEDURE**

1. Replace the driver airbag module. Please follow the Workshop Manual (WSM) procedures in Section 501-20B.

