

CERTAIN 2018 MODEL YEAR F-150 VEHICLES EQUIPPED WITH A 3.5L GTDI ENGINE — ENGINE REPLACEMENT

OVERVIEW

In all of the affected vehicles, cylinder heads are missing machined holes intended to supply lubrication to the camshaft bearing journals. Lack of proper camshaft lubrication will result in premature engine failure. Engine failure can cause a noise, a check engine light to illuminate, a runs rough condition, and/or a loss of motive power without warning while driving, increasing the risk of crash.

SERVICE PROCEDURE

1. Replace the complete engine assembly. Please follow the Workshop Manual (WSM) procedures in Section 303-01C.

