



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

December 6, 2017

Mr. David Nutley
Customer Service Manager
Bugatti
2200 Ferdinand Porsche Drive
Herndon, VA 20171

NEF-150JK
17V-764

Subject: Seat Recliner Brackets Improperly Welded

Dear Mr. Nutley:

This letter serves to acknowledge Bugatti's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:
BUGATTI/CHIRON/2017-2018

Mfr's Report Date: November 29, 2017

NHTSA Campaign Number: 17V-764

Components:
SEATS:FRONT ASSEMBLY:RECLINER

Potential Number of Units Affected: 47

Problem Description:

Bugatti is recalling certain 2017-2018 Chiron vehicles. The front seat recliner brackets may not be welded properly, which can cause the back of the seat to move unexpectedly, affecting the driver's seating position.

Consequence:

If the driver's seating position changes unexpectedly, it could increase the risk of a crash.

Remedy:

Bugatti will notify owners, and service centers will inspect the welds on the recliner brackets for both seats, replacing the seat assembly, as necessary, free of charge. The recall is expected to begin December 11, 2017. Owners may contact Bugatti customer service at 1-805-557-1050.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

We have received Bugatti's proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As required in Part 573.6(c)(6), in the case of a defect, please provide a chronology of all principal events that were the basis for the determination that the defect related to motor vehicle safety, including a summary of all warranty claims, field or service reports, and other information, with their dates of receipt. Please provide this information as soon as possible.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Jennifer Kruger who may be reached by phone at (202) 366-2461, or by email at jennifer.kruger@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,



Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement