



To: All Subaru Retailers
From: Subaru of America, Inc. - Parts & Service
Date: July 19, 2018
Re: ***Parts Return Request – Takata Inflator 98279AJ02A***

Parts Return Requested for Takata Inflator Part Number 98279AJ02A

Takata part number 98279AJ02A has been superseded by part number 98279AJ06A as a recall replacement part for the 2010-2013 Legacy/Outback. **Please refer to Product Campaign Bulletin TKA-16/17/18, TKB-16/17/18, & TKC-16/17/18.** SOA is requesting that all retailers return existing stock of part number 98279AJ02A to their facing RDC.

All part claims were entered for the retailers based on their PRIME inventory. *Please maintain sufficient inventory of 98279AJ02A to satisfy customer demand until receipt of 98279AJ06A.* Please contact your RDC Admin or the PICs with any adjustments to the claim quantity.

Please Note: All Takata recall parts must be ordered through PRIME.

IMPORTANT: Airbag inflators are considered a HAZMAT material and must be shipped following the appropriate HAZMAT shipping process (refer to Subarunet > Parts Policies/Procedure Manual

> Section 14 Parts Returns > 14.1 Returns of Hazardous Materials) or [click here](#)