

**CONDITION OF CONCERN**

The passenger side air bag inflator (recall 2318A) in this vehicle **must** be repaired at the same time as the driver side air bag inflator. Note: The driver side airbag inflator in your vehicle may be part of a small population of inflators that pose a higher risk of **explosion** in the event of a crash that causes an air bag deployment. Two inflators built at Takata on the same day as the driver side air bag inflator in your vehicle have **exploded** causing fatal injuries. **An inflator explosion could result in sharp metal fragments striking the driver or other vehicle occupants, resulting in SERIOUS INJURY OR DEATH.**

These are the same vehicles subject to Safety Recall 2218A.

**SUBJECT VEHICLES**

Model	VIN range	Build Date Range
2006 B-Series Truck	VIN List on MGSS vehicles – see MGSS for VIN's	Vehicles with a specific B-Series Takata air bag manufactured within a finite date range

**MANDATORY AIR BAG INFLATOR RETURN**

All inflator part numbers can be counted and shipped together for these returns. To schedule a return, please contact XPO at (877) 650-3476. Detailed air bag inflator return instructions are provided in Attachment IV, and can also be found on MGSS and the Dealer Assistance Group website. Failure to return the original inflator will result in a Warranty Claim Debit.

**OWNER NOTIFICATION**

Mazda will notify U.S. owners by overnight and certified mail (2 mailings) beginning January 18, 2018.

**PARTS INFORMATION**

Effective February 26, 2018, dealers will have to email the Dealer Assistance Group (DAG) to place an order for these airbag inflator parts. The DAG email address is: [corpdag@mazdausa.com](mailto:corpdag@mazdausa.com)

**NOTE: As per the Dealer Email from DAG Sent February 26<sup>th</sup>, 2018, the part you will order is a different part number. You will still receive the correct PNMC to install. Please do not attempt to order the PNMC for this recall as a stand-alone part.**

Description	Part Number	Quantity	Notes
Passenger Frontal Air Bag Inflator	1FT1-57-K50A 1FFF-57-K50A (please use for ordering)	1	Permanent Repair
Campaign Label	9999-95-065A-06	1=50 labels	Obtain in Mazda e-Store (no charge)

**WARRANTY CLAIM PROCESSING INFORMATION**

<b>Recall 2318A – PAB “Permanent” Repair **CRITICAL**</b>	<b>Replacement of Passenger Frontal Air Bag Inflator</b>
Applicable Model	B-Series
Warranty Type	R
Process Number	J1804A
Symptom Code	99
Damage Code	99
Part Number Main Cause & Quantity	1FT1-57-K50A / 1 pc *
Labor Operation Number	YY795XRX
Labor Hours	0.7 hrs.

\* From the Dealer E-Mail released on Feb 21, 2018

To provide a sufficient number of permanent remedy repair parts, Mazda has established the following two part numbers for Recall 2218A and 2318A repairs. Mazda is continually working with its suppliers to increase the number of available remedy parts for Recalls 2218A & 2318A, and for all of the Takata airbag recalls.

**NOTE: The warranty claim Part Number Main Cause is not affected by this change.**

2218A	1FFF-57-K00	B-SERIES DRIVER INFLATOR KIT
2318A	1FFF-57-K50A	B-SERIES PASSENGER INFLATOR KIT

**RENTAL CAR INFORMATION**

PLEASE CLAIM ANY RENTALS ON RECALL 2218A