

U.S. Department of Transportation

National Highway Traffic Safety Administration

January 25, 2018

Mr. Stephen Berg Indian Motorcycle Company 7290 E. Viking Blvd Wyoming, MN 55092 1200 New Jersey Avenue SE Washington, DC 20590

NEF-150JK 18V-055

Subject: Water in Wiring Harness may Keep Brake Light Lit

Dear Mr. Berg:

This letter serves to acknowledge Indian Motorcycle Company's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

INDIAN/ROADMASTER/2015-2017

Mfr's Report Date: January 16, 2018

NHTSA Campaign Number: 18V-055

Components:

ELECTRICAL SYSTEM: WIRING: REAR COMPARTMENT/TRUNK

Potential Number of Units Affected: 7,392

Problem Description:

Indian Motorcycle Company (Indian) is recalling certain 2015-2017 Roadmaster motorcycles. Water may enter the trunk wiring harness, potentially causing the brake light to remain illuminated even when the brakes are not applied.

Consequence:

If the brake light remains illuminated when the brakes are not applied, a vehicle behind the motorcycle may not know when the motorcycle is actually slowing, increasing the risk of a crash.

Remedy:

Indian will notify owners, and dealers will replace the trunk wiring harness with an updated harness that contains sealing plugs in the connectors, free of charge. The recall is expected to begin January 30, 2018. Owners may contact Indian customer service at 1-877-204-3697. Indian's number for this recall is I-18-01.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



We have received Indians' proposed owner notification letter and have approved it for distribution.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Jennifer Kruger who may be reached by phone at (202) 366-2461, or by email at jennifer.kruger@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian

Chief, Recall Management Division Office of Defects Investigations

Enforcement

