## **Recall Quarterly Report**

18V-064

Manufacturer Name : Suzuki Motor of America, Inc. NHTSA Recall No. / MFR Recall No. : 18V-064 /2A76 to 2A81 Recall Subject : Shifting with High RPMs may cause Chain to Break Owner Notification Beginning Date : JAN 25, 2018 Owner Notification End Date: JAN 25, 2018



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	APR 25, 2018	2018-1	3,097	2,074	27	0

This Document Last Updated : APR 27, 2018

## **Definitions :**

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012). Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory. Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.