

Reference	SSM73804
Models	Discovery / L462 Discovery Sport / L550 Range Rover / L405 Range Rover Evoque / L538 Range Rover Sport / L494 Range Rover Velar / L560
Title	N138 - Under Hood Petrol Fuel Leak: Injector Refit Kit Incorrect Installation Instruction
Category	Engine
Last modified	19-Mar-2018 00:00:00
Symptom	404000 Fuel System Concerns
Content	<p><u>Issue:</u> Injector Refit Kit (Service Part number: LR105428) is shipped with BOSCH installation instruction sheet. Installation instructions are incorrect on the BOSCH installation sheet.</p> <p>Affected Vehicle Range All vehicles fitted with INGENIUM I4 2.0L Petrol engine.</p> <p><u>Cause:</u></p> <ul style="list-style-type: none"> • Installation instructions are NOT in the correct order on the BOSCH installation sheet. • This leads to injector seals being damaged upon assembly. <p><u>Action:</u></p> <ul style="list-style-type: none"> • Do NOT use BOSCH installation instruction supplied with Injector Refit Kit (Service Part number: LR105428). • Follow TOPIx Workshop Manual 303-04C: Fuel Charging and Controls - INGENIUM I4 2.0L Petrol - Removal and Installation: Fuel Injectors. <p>Technicians - Please rate this SSM and provide comments so that future communications can be improved.</p> <p>1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.</p> <p>3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.</p> <p>5 = Excellent – All required information provided to resolve the customer concern.</p>

