

New Safety Recalls N138 and H081 AJ200 4 Cyl Gasoline Engines



- New safety recalls were announced February 7th affecting certain 18MY Jaguar and Land Rover models fitted with 4 cyl AJ200P gasoline engines. Service Bulletins have been emailed and posted to Infotrail and JBN.
- Models affected:
 - Jaguar 18MY XF/XE/F-PACE/E-PACE and F-TYPE
 - Land Rover 18MY Discovery Sport, Evoque and 18MY Range Rover Velar
- Defect: The brazing of the engine fuel rail end caps is inconsistent and may not meet the design condition, so not sealing the fuel rail ends. Fuel vapor and liquid fuel leaks can occur over time. This can lead to a liquid fuel leak into the engine bay.
- There are several reports of fuel leaks but there have been no reports of accidents, injuries or fires.
- Affected vehicles will need a replacement fuel rail.
- Parts and technical repair bulletins are expected to be available week of March 19th 2018
- Check DDW to confirm which vehicles are affected. A list of unsold VIN by retailer will be published on JBN/Infotrail
- Affected new cars must not be sold prior to completing the recall repair.
- Please refer to the published service bulletins for additional information. These bulletins will be updated as additional information becomes available.
- Customer notification is scheduled for March 23rd