



IMPORTANT SAFETY RECALL

Re: VIN [SEE ATTACHED LIST]

NHTSA Recall 18V-145

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Morgan Truck Body, LLC (Morgan) has decided that a defect that related to motor vehicle safety exists in your vehicle with the VIN stated above. Morgan has found that the rear turn signals on certain chassis using an Electrical Foreign to Domestic Converter Harness may malfunction, increasing the risk of a crash.

What is the Concern:

Morgan has identified an issue with the Electrical Foreign to Domestic Converter Harnesses manufactured by Grote and installed on certain Morgan truck bodies mounted on Isuzu, Chevrolet, Freightliner, GMC, Kenworth, Mercedes, Mitsubishi and Peterbilt chassis. Some of these converter harnesses have experienced a failure due to water ingress. The water ingress may cause the rear turn signals to malfunction in several different ways including becoming inoperable, bleed through of low intensity light to the rear tail/tum signal lamp, or other turn signal or 4-way flasher malfunctions.

What Should You Do?

The vehicle(s) listed on the attachment were sold to you and have been identified as vehicle(s) that include the aforementioned converter harnesses and module. Please confirm ownership of the vehicle(s), and contact your local Morgan Authorized Repair Center to make an appointment to have your vehicle retrofitted. The Repair Center will complete the retrofit at no cost to you.

How Long Will the Repair Take?

Please plan to leave your vehicle with the dealer for half a day to allow the Repair Center time to complete the retrofit. A complete list of Morgan's network of Authorized Repair Centers can be found on Morgan's Website at <https://www.morgancorp.com/service/>

What is the affected component?

Grote Industries Electrical Foreign, to Domestic Converter Harness and Hopkins Electronic taillight converter [Morgan Part# 0410197 -OR- Morgan Part# 0410195].