OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

# 18V-146

**Manufacturer Name:** Triple E Recreational Vehicles

**Submission Date:** MAR 05, 2018 **NHTSA Recall No.:** 18V-146 **Manufacturer Recall No.:** CA#8930-1



#### **Manufacturer Information:**

Manufacturer Name: Triple E Recreational Vehicles

Address: PO Box 1230 Winkler MB

Canada 00 R6W 4C4

Company phone: 204-325-4361

# **Population:**

Number of potentially involved : 995 Estimated percentage with defect : 100 %

#### **Vehicle Alterer Information:**

Vehicle 1: 2017-2018 UNITY ALL MODELS

Descriptive Information: The OCCC (Occupant & Cargo Carrying Capacity) decal & Tire decal has the

incorrect OCCC amount. These decals are indicating more OCCC weight than the actual amount. The OCCC weight has been calculated by a computer generated formula, which was inputted incorrectly. Prior to this it was manually calculated.

Production Dates: SEP 13, 2016 - FEB 23, 2018

Vehicle 2: 2017-2018 WONDER ALL MODELS

Descriptive Information: The OCCC (Occupant & Cargo Carrying Capacity) decal & Tire decal has the

incorrect OCCC amount. These decals are indicating more OCCC weight than the actual amount. The OCCC weight has been calculated by a computer generated formula, which was inputted incorrectly. Prior to this it was manually calculated.

Production Dates: SEP 13, 2016 - FEB 23, 2018

Vehicle 3: 2017-2018 SERENITY S24CB

Descriptive Information: The OCCC (Occupant & Cargo Carrying Capacity) decal & Tire decal has the

incorrect OCCC amount. These decals are indicating more OCCC weight than the actual amount. The OCCC weight has been calculated by a computer generated formula, which was inputted incorrectly. Prior to this it was manually calculated.

Production Dates: SEP 13, 2016 - FEB 23, 2018

#### **Description of Noncompliance:**

Description of the The OCCC (Occupant & Cargo Carrying Capacity) decal & Tire decal has been Noncompliance: calculated incorrectly indicating more OCCC weight than the actual amount.

FMVSS 1: NR FMVSS 2: NR Description of the Safety Risk: As a result, the vehicle could be overloaded, which would result in poor

vehicle handling characteristics increasing the risk of a crash causing injury

and/or damage to property.

Description of the Cause: The formula to calculate the OCCC was inputted into a computer generated

calculation program incorrectly.

Identification of Any Warning N/A

that can Occur:

#### **Supplier Identification:**

# **Component Manufacturer**

Name: NR Address: NR

NR

Country: NR

#### **Chronology:**

An in-house inspection of the OCCC weight calculation was done and found the calculation formula was incorrect.

## **Description of Remedy:**

Description of Remedy Program: Triple E RV will provide two new OCCC decals and one Tire decal, send to

Dealers & Retail Owners with instructions to adhere these three new decals. If the Retail Owners choose to have a servicing center perform the recall, the retail owner will be reimbursed or the servicing center will be paid directly by Triple E RV. The Dealer will submit a warranty claim for

the time allotted to perform the recall.

How Remedy Component Differs The new decals will have a lower OCCC weight amount. FD-331 OCCC FD-

from Recalled Component :

Identify How/When Recall Condition At this time the IT department has corrected the calculation formula in the

was Corrected in Production: program.

## **Recall Schedule:**

Description of Recall Schedule: NR

Planned Dealer Notification Date: MAR 12, 2018 - MAR 15, 2018 Planned Owner Notification Date: MAR 12, 2018 - MAR 15, 2018

#### **Purchaser Information:**

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name:

Address:

Country:

**Company Phone:** 

<sup>\*</sup> NR - Not Reported