

March 7, 2018

Version 1

Safety Recall: Left (Driver Side) Second Row Seat Recliner Does Not Lock

AFFECTED VEHICLES

Year	Model	Trim	VIN Range
2014-16	Odyssey	ALL	Check the iN VIN status for eligibility.

BACKGROUND

Some 2014-16 Odyssey vehicles have an internal problem in the recliner mechanism on the left (driver side) second row seat that may prevent the seat back from locking. If a vehicle with an unlocked seat back is involved in a crash, the seat will not operate as designed to protect the occupant, leading to increased potential for injury or death. Affected vehicles are on **STOP SALE** until further notice.

Do not call Tech Line for updates.

This bulletin will be revised in the future once the repair procedure, parts information, and warranty claim information are available.

END

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.