ATTENTION: Dealer Principal, Warranty Manager, Service Manager, Parts Manager

Freightliner Dealers – Ü.S. and Canada Western Star and Sterling Dealers – U.S. and Canada FCCC Dealers – U.S. and Canada Direct Warranty Customers – U.S. and Canada Export Distributors

Daimler Trucks North America LLC

WARRANTY CAMPAIGNS DEPARTMENT

P.O. Box 4090 800-547-0712 Portland, Oregon 97208-4090

> If you have questions about this Letter, please submit your inquiry on the Web using the WSC Link on DTNAConnect

REF #: ICI18-037

Effective: 12/01/18
Release: 11/30/18

SUBJECT: FL766 - Second Revised Bulletin

This letter is to inform you that a second revised bulletin for Recall *FL766 Western Star Power Cable Studs* is available on DTNAConnect. Please print and use the revised bulletin for all work under FL766 from this point forward.

SECOND REVISION: Vehicles will require either the 1/4 inch or the 3/8 inch power stud. A step has been added to the Power Cable Stud Replacement procedure to check for the power stud size. The Replacement Parts Table has been updated to include both power studs sizes. Please handle vehicles in FL766 as follows:

INT FL766 & FL766A

- Vehicles that WERE NOT inspected under INT FL766 or FL766A have been moved to FL766B.
- Vehicles that WERE inspected under INT FL766 or FL766A and PASSED, are complete and no further work is needed.
- Vehicles that WERE inspected under INT FL766 or FL766A and did NOT PASS, have been moved to FL766C.

FL766B - Perform FL766 (no work has been done on these vehicles).

FL766C - Perform FL766 (these vehicles failed the interim inspection and further work is needed).

If you have questions or need further information, contact the Warranty Campaigns Departement by submitting an inquiry through the WSC Link on DTNAConnect.

The information contained in this letter supercedes and supplements any related policies and procedures in any previously released bulletins, the Warranty Manual, and/or previously released letters. Failure to read or distribute this letter will not exempt addressees from compliance with the information contained herein.