AMENDED DEFECT INFORMATION REPORT 18V-221 April 25, 2018



Since filing the original Defect Information Report on April 5, 2018, Honda has confirmed that the affected vehicle population incorrectly included seventeen (17) 2018 model year Honda Pilot LX vehicles. These LX trim vehicles are originally equipped with driver and front passenger manual seats and the recall is specific to driver and front passenger powered seats assembled with improperly manufactured seat rivets. The identification of potentially affected vehicles and the total number of potentially affected vehicles are being amended to reflect this update.

573.6(c)(2)

Identification of potentially affected vehicles:

See below for VIN range and date of manufacture updates.

Make / Model /

Previous VIN Range / Dates of

New / Current VIN Range / Dates of

Model Year

Manufacture

Manufacture

2018 Honda Pilot

5FNYF5H91JB003459 -

5FNYF5H1XJB006189

5FNYF5H91JB003459 -5FNYF5H99JB005685

1/02/2018 - 1/20/2018

1/02/2018 - 1/12/2018

573.6(c)(3)

Total number of potentially affected vehicles: see below for population update.

Previous Population

New / Current Population

5,827

5,810