

"Manufacturer Certification Label"

What is the issue with the affected vehicles?

Vehicles were equipped with a Manufacturer Certification Label that lists an incorrect weight limit.

What is the cause of this condition?

Wrong information inside our production system.

What effect does the condition have?

If the listed weight limit is incorrect on the Manufacturer Certification Label the vehicle may be overloaded exceeding the gross vehicle weight rating (GVWR), thereby increasing the risk of an accident.

Is there any risk for the car occupants?

Automobili Lamborghini S.p.A. is not aware of any accidents or other incidents resulting in injury to a person or damage to property.

■ Can I still use the vehicle ?

Yes, the affected vehicles can continue to be driven as usual, but until this recall repair has been performed, do not rely on the rear axle weight limit shown on the Manufacturer Certification Label.

Which vehicles are affected ?

Lamborghini Centenario Coupè and Roadster model year 2017.

How many vehicles are affected worldwide ?

23 units

What exactly needs to be repaired on the car?

Install a corrected Manufacturer Certification Label.

■ How long will the repair work take?

Normally, the repair work will take from 30 minutes to 1 hour.

■ Will Automobili Lamborghini S.p.A. bear the costs of the repair work?

The costs of this campaign will be borne entirely by Automobili Lamborghini S.p.A.

■ Where can I have the repair work carried out ?

Any authorized Lamborghini dealer and Service point worldwide.

Is it necessary to make an appointment at the workshop?

Yes, customer should contact an authorized Lamborghini dealer or Service point.