



## Thor Motor Coach Recall Repair Instructions

Recall #	<b>18V-385 2018-302</b>		
Description/Title:	<b>MORryde U-Bolts Torque</b>		
Affected Product Line(s):	<b>Certain MY 2019 2019 Chateau, Four Winds, Freedom Elite, Majestic, Outlaw, Quantum, and Vegas motorhomes</b>		
Service Campaign # :	<b>RC000156</b>	Released Date:	<b>06/20/2018</b>
Repair Code:	<b>TMCRC80473V</b>	Document Date:	<b>06/20/2018</b>
Time Allowed:	<b>0.5</b>	Document Revision:	<b>A</b>

### Issue:

On certain model year 2019 Chateau, Four Winds, Freedom Elite, Majestic, Outlaw, Quantum, and Vegas motorhomes, MORryde International, Inc. notified TMC that Ford E-450 units that had wheelbase modifications during the dates of March 6<sup>th</sup>, 2018 through April 18<sup>th</sup>, 2018, have unverified u-bolt torque and are affected by this recall. Insufficient torque on the u-bolts may cause the u-bolts to loosen or break, resulting in the potential for the rear axle to break away from the chassis. This could lead to loss of control over the vehicle and increase the risk of a crash causing injury and/or damage to property.

### Instructions:

Please reference the pdf attachment “U-Bolt Recall Instructions” for MORryde’s recall repair instructions.

**NOTE:** To request approval for additional time over the allotted amount to complete the repair, please contact MORryde directly at [warranty@morryde.com](mailto:warranty@morryde.com). Please be sure to obtain the approval # to reference when submitting the authorization to TMC.