



Overseas Automobile Service Group
SUZUKI MOTOR CORPORATION
 300 Takatsuka, Minami, Hamamatsu, JAPAN 432-8611
 Tel: 81-53-440-2977, Fax: 81-53-440-2318

Page 1 of 2
 Date Sep. 25, 2018
 Our ref. SB-180925

To: Selected Suzuki Automobile Distributors
 Attn.: Managing Director
 Service Director or Manager

**Subject: Additional Affected VINs on 99-SB Safety Recall Campaign
 For Power Steering Tensioner Pulley Damage.**

Dear Sirs and Madams,

This letter is to inform you of an expansion in the range of vehicles to be involved in the Safety Recall Campaign which has been notified by the attached letter SB-100602 issued on June 2, 2010. .

We have found insufficient vehicles in the affected VIN list which was attached to the Campaign Letter said above. Some affected VINs for JB627W and JA627W were missing from the VIN list.

We are sending the additional affected VIN list. You are kindly requested to add these VINs to your file.

Warranty Reimbursement

Due to 49160-77E01-RX0 was superseded by 49160-77E01 as regular parts, campaign claim application manner should be changed as below. This manner is applied to not only claims with additional VINs but also those with preexisting VINs.

Claim Category		2 (Campaign Claim)	
Trouble Code		99-SB	
Basic Code		LJ9999	
Labor Allowance		0.1h (for inspection Only) 0.6h (Inspection and Replacement)	
Causal Part No.	Q'ty	Replacement Parts No.	Q'ty
49160-77E01-RX0	0	49160-77E01	1

We are very sorry for causing inconvenience to you. Your cooperation and assistance will be highly appreciated. If you have any questions, please don't hesitate to contact us anytime.

Very truly yours,



Shinji Ishikawa
Department General Manager
Overseas Service Department
SUZUKI MOTOR CORPORATION

Attachment

Reference: Safety Recall Campaign Letter SB-100602

ANNEX1: Additional affected VIN list