

Page 1 of 1 Date Oct. 29, 2018 Our ref. CY-181029

SUZUKI MOTOR CORPORATION

Overseas Automobile Service Group Overseas Service Department 300 Takatsuka, Minami, Hamamatsu, JAPAN 432-8611 Tel: 81-53-440-2977, Fax: 81-53-440-2318

To: Selected Suzuki Automobile Distributors

Attn.: Managing Director

Service Director / Manager

SUBJECT: A6B424 (KIZASHI) Vehicles Market Action for Fuel Tank Crack

Dear Sirs,

We regret to inform you that certain A6B424 (KIZASHI) vehicles may experience a check engine light ON with fuel odor.

We would like to request you to take the following actions.

1. Condition

A large amount of sand enter into the suction pipe which provides fresh air to the canister, and the suction pipe might be blocked with sand. Due to this blockage, excessive negative pressure could be generated in the fuel tank, causing the fuel tank deformation and crack. If this occurs, the fuel odor is smelled and the check engine light is turned on. Cause is still under investigation.

2. Affected Vehicles Information

(1) Model : A6B424 vehicles produced in Japan.

(2) Production Period: From Oct. 13, 2009 through Oct. 31, 2012

(3) Vehicles : US territories: 21,052 units (US main land: 20,444 units)

3. Action

Please notify this information to customers by November 16, 2018 referring to Annex 1, VIN list and Annex 2, Sample letter for owners.

We are very sorry for causing inconvenience to you. Your cooperation and assistance will be highly appreciated. If you have any question, please don't hesitate to contact us anytime.

Very truly yours,

Shinji Ishikawa

Department General Manager Overseas Service Department SUZUKI MOTOR CORPORATION

Attachment : Annex 1, VIN List, Annex 2, Sample letter for owners