



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

February 26, 2019

Mr. Gerrit Hurenkamp
Director of Engineering
Arcimoto Inc
2034 W. 2nd Ave
Eugene, OR 97402

NEF-150JK
18V-938

Subject: Brake Warning Light Missing/FMVSS 122

Dear Mr. Hurenkamp:

This letter serves to acknowledge Arcimoto Inc's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

ARCIMOTO/FUV/2017-2018

Mfr's Report Date: December 31, 2018

NHTSA Campaign Number: 18V-938

Components:

SERVICE BRAKES, HYDRAULIC:SWITCHES:BRAKE WARNING

Potential Number of Units Affected: 22

Problem Description:

Arcimoto Inc (Arcimoto) is recalling certain 2017-2018 FUV motorcycles. The affected motorcycles do not have a service brake warning light to warn the operator if there is a brake system malfunction. As such, these vehicles fail to comply with Federal Motor Safety Standard (FMVSS) number 122, "Motorcycle brake systems."

Consequence:

If the operator unknowingly operates the motorcycle with a problem in the brake system, there would be an increased risk of a crash.

Remedy:

Arcimoto has notified all affected owners and the motorcycles are within the manufacturer's control. Arcimoto will update the service brake warning light software, free of charge. Owners may contact Arcimoto customer service at 1-541-683-6293. Arcimoto's number for this recall is 7F7-H7M4W-12.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov

Under 49 U.S.C. § 30112(a), it is illegal for anyone, including a manufacturer, distributor, dealer, or retailer to sell an item of equipment or vehicle that fails to comply with all applicable Federal motor vehicle safety standards.

It is our understanding that notification to owners began prior to our review of the owner notification letter. Should it become necessary for Arcimoto to do a renotification, the follow-up notification must be submitted to this office for review and it must comply with the requirements of Part 577.5, "Notification pursuant to a manufacturer's decision" and Part 577.10, "Follow-up notification."

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Jennifer Kruger who may be reached by phone at (202) 366-2461, or by email at jennifer.kruger@dot.gov. We look forward to working with you.

Sincerely,



Kareem Habib
Acting Chief, Recall Management Division
Office of Defects Investigations
Enforcement