



Indian Motorcycle
Company
P.O. Box 47700
Medina, MN 55340-9960

IMPORTANT SAFETY NOTICE
This notice applies to your vehicle
Recall Campaign: **19E-007**

Subject: **2015-2019 Indian Scout / Sixty / Bobber Motorcycles
equipped with the Black Clutch and Brake Lever Accessory
Kit (pn 2883795-658)**

PLEASE READ IMMEDIATELY

VIN: I-19-01
First Name Last Name
Address
City, State ZIP

Dear Indian Motorcycle Owner,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. This is to inform you that your vehicle may contain a defect that could affect the safety of a person. Our records show you have purchased an affected vehicle.

The reason for this notice:

Indian Motorcycle has identified a potential assembly concern affecting the black Clutch and Brake Lever Accessory Kit (PN: 2883795-658), for use with Indian Scout, Scout Sixty and Bobber models. This affects the brake lever portion of the kit, which may not have been assembled to specification. The free-play adjustment screw may not be correctly installed and can result in front brake drag, unintentional front brake application, and potentially locking of the front wheel, increasing the risk of a crash.

What you should do:

Contact your authorized Indian Motorcycle dealer to schedule an appointment to have the repairs performed. Do not attempt repairs yourself. Repairs must be done only by an authorized Indian Motorcycle dealer. This repair should take approximately 18 minutes. When making contact with your dealer, discuss parts availability, their schedule and how long they will need to keep your vehicle.

What your dealership will do:

Indian Motorcycle will issue a Safety Bulletin to all Indian Motorcycle dealers, with instructions required to replace the brake lever. This work will be performed by your dealer at no cost to you.

This notice was mailed to you according to our most current registration information. If you no longer own this vehicle, or if some of the contact information in this notice is incorrect, please contact your dealer to complete a transfer of ownership. Federal law requires that any vehicle lessor receiving this notice must forward a copy of this notice to the lessee within 10 days.

If you need assistance contacting or locating an Indian Motorcycle dealer, or if you have questions your Indian Motorcycle dealer is not able to address, contact our Indian Motorcycle Owner Connections Department at 1-877-204-3697, scan the QR code, or go to <https://www.indianmotorcycle.com/en-us/self-help/>.



If you believe that Indian Motorcycle has failed to remedy this defect without charge or is unable to do so within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue SE., Washington, D.C. 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or on the web go to www.safercar.gov.

We apologize for this inconvenience and assure you that we are committed to customer satisfaction and providing world-class products for riders to enjoy.

Sincerely,

Indian Motorcycle Company

For the latest updates to this safety recall, or to check if your vehicle is part of another safety recall, scan the QR code, or go to www.polaris.com/en-us/on-road-recalls/.

